

- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



### survey report on:

	Property address       95 Guardwell Crescent, Edinburgh, EH17 7HA
--	---

Customer	Mr David Donaldson, Ms Joanne Inch
----------	------------------------------------

EH17 7HA		95 Guardwell Crescent, Edinburgh, EH17 7HA
----------	--	--

Prepared by	Harvey Donaldson And Gibson
-------------	-----------------------------

Date of inspection	12th February 2018	
· ·	,	



HARVEY DONALDSON & GIBSON CHARTERED SURVEYORS

95 Guardwell Crescent, Edinburgh, EH17 7HA 12th February 2018 QR241870

### PART 1 - GENERAL

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Х

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

### Terms and Conditions

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

### **PART 2 - DESCRIPTION OF THE REPORT**

### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	Two storey detached house.
Accommodation	Ground Floor: Entrance Hall, Living Room, Kitchen/Dining Room, Utility Room and separate WC compartment. First Floor: Landing, Three Bedrooms, Bathroom and en-suite Shower Room.

Gross internal floor area (m²)	127 approximately (including garage).
Neighbourhood and location	Established residential development where surrounding properties are of a similar age, type and character. Local facilities and amenities are available within fairly easy reach.

Age	22 years approximately

Dry and cold.

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	Facing brick construction.

Weather

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	Pitched timber construction overlaid in tiles. Restricted roof void inspection due to part laid flooring, insulation and heavily stored items within this area.
	The roof to the extension is pitched and tiled. There is no roof void area available for inspection to the extension.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	UPVC materials.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	Modern timber frame inner leaf construction with a masonry exterior, and render/facing brick finishes externally. The extension appears of similar construction.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The window units are predominately of original timber framed double glazed units, with UPVC double glazed units to the extension. There are Velux style double glazed units to the extension roof. The access doors are of timber, a composite and UPVC construction.

External decorations	Visually inspected.
	External timbers are paint finished.
Conservatories / porches	N/A

N/A.

**Communal areas** 

Garages and permanent outbuildings	Visually inspected.
	Single integral garage. Stored items were in place at the time of inspection.
Outside areas and boundaries	Visually inspected.
	Private grounds to the front, side and rear, including a driveway to the front.
Ceilings	Visually inspected from floor level.
	Plasterboard construction or similar.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Plasterboard construction.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring appears of timber construction throughout. Fitted floor coverings throughout. No inspection of any sub-floor area.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Skirtings, facings and door surrounds are of timber construction. The kitchen contains wall and base mounted units.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is a gas fire installed within the property.
Internal decorations	Visually inspected.

visually hispected.
Emulsion paint/wallpaper finish.

Cellars	N/A.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Where seen pipework is run in plastic and metal materials. The bath and shower rooms provide three piece suites.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Gas fired boiler serving radiators throughout the property. The boiler is located within the garage. Hot water is assumed supplied from the central heating system via the hot water tank adjacent to the boiler.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is believed to be connected to mains drainage.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	Smoke detectors appears fitted.

Any additional limits to inspection	The property was inspected within the limits imposed by occupation which included fitted floor coverings, stored items, furnishings etc. The owner's personal belongings were not removed from cupboards.
	It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.
	This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.
	No removal of internal linings has been carried out in order to ascertain the condition of hidden parts and no warranty can be given regarding the areas not specifically referred to in this report.
	The external building fabric has been inspected from ground level only from the subjects grounds and where possible from adjoining public property. Exposure work has not been carried out.
	Where walls are lined internally, for example with plasterboard, tiling or timber, the structure behind the lining could not be tested with an electronic moisture meter.
	No access was gained to any sub-floor area within the building.
	Flooring beneath the bath/shower could not be inspected.



### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No visible evidence of significant structural movement was noted within the limitations of the inspection.

Dampness, rot and infestation	
Repair category	1
Notes	An electronic moisture meter was used to measure levels of dampness, at random locations, to lower wall surfaces and floors, where accessible and without moving furniture or lifting floor coverings, if present. No obvious significant dampness, timber decay or infestation noted, within the limitations imposed on the inspection.

Chimney stacks	
Repair category	1
Notes	From a ground level inspection, no obvious significant defects were noted to the chimney head, allowing for normal weathering.

Roofing including roof space	
Repair category	1
Notes	The roof coverings appear to be in a generally satisfactory condition commensurate with its age and nature of construction. On the date of inspection some isolated deterioration was noted to the ridge pointing. This is understood to have been repaired and we have had sight of a photograph in relation to this. There is some moss growth on the roof tiling and some moss/vegetation within the valley gutter details.

Rainwater fittings	
Repair category	1
Notes	No significant disrepair was noted to rainwater goods. It will however be appreciated that the inspection was carried out during dry weather conditions. Sometimes defects in rainwater goods are only apparent during, or after heavy rainfall. We would refer to 'Roofing including roof space'.

Main walls	
Repair category	1
Notes	The walls appear generally satisfactory allowing for normal weathering. On the date of inspection some isolated hairline cracked render was noted. This is understood to have been repaired and we have had sight of a photograph in relation to this.

Windows, external doors and joinery	
Repair category	1
Notes	The window units are predominately original to the construction of the property and appear generally satisfactory allowing for age, although window timbers/paintwork are showing signs of some weathering and deterioration. On the date of inspection mastic pointing around window and door openings was noted to be defective in places. This is understood to have been repaired and we have had sight of photographs in relation to this and it is assumed that all areas have been repaired where necessary.

External decorations	
Repair category	1
Notes	The external decorations appear mostly in reasonable condition but are beginning to deteriorate in places

Conservatories/porches	
Repair category	-
Notes	N/A.

Communal areas	
Repair category	-
Notes	N/A.

Garages and permanent outbuildings	
Repair category	1
Notes	The garage appears in reasonable condition having regard to its age and intended purpose.

Repair category     1	
Notes       The outside areas and boundaries appear generally adequate for purpor         On the date of inspection a gap was noted between the boundary wall a the house. This is understood to have been filled and we have had sight photograph in relation to this.         There are mature trees in some proximity to the property. Trees can cau damage to structures and services. The requirement for gutter maintena should also be recognised along with the risk of storm damage.	nd side of t of a use

Ceilings	
Repair category	1
Notes	The ceilings are cracked in places but appear reasonably sound allowing for their age.

Internal walls	
Repair category	1
Notes	The internal walls appear in reasonable condition for their age.

Floors including sub-floors	
Repair category	1
Notes	Areas of loose/squeaky flooring were noted.

Internal joinery and kitchen fittings	
Repair category	1
Notes	The internal joinery and kitchen units appear satisfactory.

Chimney breasts and fireplaces	
Repair category	1
Notes	All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.

Internal decorations	
Repair category	1
Notes	The internal decorations appear satisfactory.

Cellars	
Repair category	-
Notes	N/A.

Electricity	
Repair category	1
Notes	The system appears adequate for present day use. The electrical installation appeared to be in a condition commensurate with age and type with no visual defects being apparent. However, it should be fully appreciated that only the most recently re-wired or constructed properties will comply with current regulations. It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands.

Gas	
Repair category	1
Notes	All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.

F- Water, plumbing and bathroom fittings	
Repair category	1
Notes	The plumbing installation appeared generally satisfactory commensurate with its type and age.
	The sanitary fittings are of a modern type and appeared satisfactory commensurate with their type and age.

Heating and hot water	
Repair category	1
Notes	There is a gas fired central heating system. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor. It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.

Drainage	
Repair category	1
Notes	No obvious significant defects were noted to the drainage system, within the limitations of the inspection.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. Accessibility information

### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground Floor	
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No	
3. Is there a lift to the main entrance door of the property?	Yes No X	
4. Are all door openings greater than 750mm?	Yes No X	
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No	
6. Is there a toilet on the same level as a bedroom?	Yes X No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X	
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No	

### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The tenure is understood to be outright ownership.

If the legal advisers find that there are significant variations from the standard assumptions then this should be referred back to the surveyor.

The property has been extended. The valuation is given on the assumption that full certification in respect of the planning permissions, building warrants and completion certificates were issued for these works.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

### Estimated reinstatement cost for insurance purposes

£230,000 (Two hundred and thirty thousand pounds sterling).

#### Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on 12th February 2018 is £325,000 (Three hundred and twenty five thousand pounds sterling).

Signed	Security Print Code [487544 = 5210 ]O
	Electronically signed

Report author	Jamie Biggar
---------------	--------------

Company name	Harvey Donaldson And Gibson

Address 8	8 Manor Place, Edinburgh, EH3 7DD
-----------	-----------------------------------

Date of report	23rd February 2018	

### Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	95 Guardwell Crescent, Edinburgh, EH17 7HA Mr David Donaldson, Ms Joanne Inch 12th February 2018
Property Details	
Property Type	X House       Bungalow       Purpose built maisonette       Converted maisonette         Purpose built flat       Converted flat       Tenement flat       Flat over non-residential use         Other (specify in General Remarks)
Property Style	X       Detached       Semi detached       Mid terrace       End terrace         Back to back       High rise block       Low rise block       Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	elieve that the property was built for the public sector, Yes X No nilitary, police?
Flats/Maisonettes on	Iy       Floor(s) on which located       No. of floors in block       Lift provided?       Yes       No         No. of units in block       Image: State of the state o
Approximate Year of	
Tenure	
X Absolute Ownership	Leasehold     Ground rent £     Unexpired years
Accommodation	
Number of Rooms	1       Living room(s)       3       Bedroom(s)       1       Kitchen(s)         2       Bathroom(s)       1       WC(s)       1       Other (Specify in General remarks)
	cluding garages and outbuildings) 127 m <sup>2</sup> (Internal) 146 m <sup>2</sup> (External) (greater than 40%) X Yes No
Garage / Parking /	Outbuildings
X Single garage Available on site?	Double garage       Parking space       No garage / garage space / parking space         X Yes       No
Permanent outbuildin	igs:

### Mortgage Valuation Report

Construction							
Walls	Brick	Stone	Concrete	X Timber frame	Other	(specify in Gen	eral Remarks)
Roof	X Tile	Slate	Asphalt	Felt	Other	(specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struct	ural moveme	nt?			Yes	X No
If Yes, is this rece	nt or progress	ve?				Yes	No
Is there evidence, immediate vicinity		son to antici	pate subsidence	, heave, landslip (	or flood in the	Yes	X No
If Yes to any of the	e above, provi	de details in	General Remark	S.			
Service Connec	tion						
Based on visual ir of the supply in G			es appear to be	non-mains, pleas	e comment or	n the type ar	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description o	of Central Heat	ing:					
Site							
Apparent legal iss	ues to be verif	ied by the co	onveyancer. Plea	se provide a brief	f description ir	n General Re	emarks.
Rights of way	Shared drive	s / access	Garage or other	amenities on separate	e site	ed service conn	ections
Ill-defined boundar	ies	Agricult	ural land included wi	th property	Other	· (specify in Ger	neral Remarks)
Location							
Residential suburb	X Resi	dential within to	wn / city 🗌 Mixe	ed residential / comme	rcial 🗌 Mainl	y commercial	
Commuter village	Rem	ote village	Sola	ted rural property	Other	· (specify in Gei	neral Remarks)
Planning Issues	\$						
Has the property b	been extended	/ converted	/ altered? X	Yes 🗌 No			
If Yes provide deta	ails in General	Remarks.					
Roads							
X Made up road	Unmade road	Partly	completed new road	Pedestrian a	access only	Adopted	Unadopted

#### **General Remarks**

The general condition of the property appears consistent with its age and type of construction, but some works of repair/maintenance are required.

The property has been extended. The valuation is given on the assumption that full certification in respect of the planning permissions, building warrants and completion certificates were issued for these works.

The 'other' accommodation is Utility Room.

#### **Essential Repairs**

Estimated cost of essential repairs £	Retention recommended?	X No	Amount £	

### Mortgage Valuation Report

### **Comment on Mortgageability**

The property affords adequate security for loan purposes based on the valuation figure.

Valuations	
Market value in present condition	£ 325,000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 230,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No
Declaration	

Signed	Security Print Code [487544 = 5210 ]O Electronically signed by:-
Surveyor's name	Jamie Biggar
Professional qualifications	MRICS
Company name	Harvey Donaldson And Gibson
Address	8 Manor Place, Edinburgh, EH3 7DD
Telephone	0131 2257668
Fax	0131 2258690
Report date	23rd February 2018

### **Energy Performance Certificate (EPC)**

### Scotland

Dwellings

### 95 GUARDWELL CRESCENT, EDINBURGH, EH17 7HA

Dwelling type:	Detached house
Date of assessment:	12 February 2018
Date of certificate:	12 February 2018
Total floor area:	114 m <sup>2</sup>
Primary Energy Indicator:	254 kWh/m <sup>2</sup> /year

**Reference number:** Type of assessment: Approved Organisation: Main heating and fuel:


3118-6122-5100-0762-2992 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas


#### You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,222	See your recommendations
Over 3 years you could save*	£279	report for more information

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions







### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (67). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$ emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (60)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Floor insulation (suspended floor)	£800 - £1,200	£141.00	<b></b>
2 Solar water heating	£4,000 - £6,000	£138.00	<b></b>
3 Solar photovoltaic (PV) panels	£5,000 - £8,000	£813.00	<b></b>

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE** 

### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★★☆
Roof	Pitched, 200 mm loft insulation Pitched, insulated (assumed)	★★★★☆ ★★★★☆	★★★★☆ ★★★★☆
Floor	Suspended, limited insulation (assumed) Suspended, insulated (assumed)		_
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	Room heaters, mains gas	_	_
Hot water	From main system	★★★★☆	<b>★★★★</b> ☆
Lighting	Low energy lighting in all fixed outlets	****	****

### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 45 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.1 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

### 95 GUARDWELL CRESCENT, EDINBURGH, EH17 7HA 12 February 2018 RRN: 3118-6122-5100-0762-2992

savings

ld

79 ars

Estimated e	nergy c	osts for this home		
		Current energy costs	Potential energy costs	Potential future
Heating		£2,586 over 3 years	£2,463 over 3 years	
Hot water		£414 over 3 years	£258 over 3 years	You coul
Lighting		£222 over 3 years	£222 over 3 years	save £27
	Totals	£3,222	£2,943	over 3 yea

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indiantics and	Typical saving	Rating after improvement		Green
Re	commended measures	Indicative cost	per year	Energy	Environment	Deal
1	Floor insulation (suspended floor)	£800 - £1,200	£47	D 68	D 62	$\bigcirc$
2	Solar water heating	£4,000 - £6,000	£46	C 70	D 65	
3	Solar photovoltaic panels, 2.5 kWp	£5,000 - £8,000	£271	C 78	C 72	

Measures which have a green deal tick  $\bigcirc$  are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick  $\bigcirc$  may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### 2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

### 3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	12,427	N/A	N/A	N/A
Water heating (kWh per year)	2,938			

### 95 GUARDWELL CRESCENT, EDINBURGH, EH17 7HA 12 February 2018 RRN: 3118-6122-5100-0762-2992

### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number:	Mr. Jamie Biggar EES/017267
Company name/trading name:	Harvey Donaldson & Gibson Chartered Surveyors
Address:	8 Manor Place
	Edinburgh
	EH3 7DD
Phone number:	01312257668
Email address:	jamie.biggar@hdg.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

### Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.





## property questionnaire

12 February 2018

E	5 Guardwell Crescent dinburgh H17 7HA
---	---

Seller(s)	Mr and Mrs D Donaldson

### Note for sellers

**Completion date of property questionnaire** 

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

### Note for buyers

• Before marketing the property, the solicitor or estate agent acting on behalf of the client(s) will have retained a signed copy of this completed questionnaire. This may be viewed by arrangement with the solicitor or estate agent.

### Information to be given to prospective buyer(s)

1.	Length of ownership			
	How long have you owned the property?	3 years 6 months		
2.	Council tax			
	Which Council Tax band is your property in?	F		
3.	Parking			
	What are the arrangements for parking at your property?         (Please tick all that apply)         Image         Image			
4.	Conservation area			
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	No		
5.	Listed buildings			
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	No		

6.	Alterations/additions/extensions					
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	No				
	<u>If you have answered yes</u> , please describe below the changes which you have made:					
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?					
	<u>If you have answered yes</u> , the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.					
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:					
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	No				
	If you have answered yes, please answer the three questions below:					
	(i) Were the replacements the same shape and type as the ones you replaced?					
	(ii) Did this work involve any changes to the window or door openings?					
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):					
	Please give any guarantees which you received for this work to your solicitor or estate agent.					

7.	Central heating					
а.	Is there a central heating system in your property?	Yes				
	(Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).					
	<u>If you have answered yes or partial</u> , what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).					
	Gas fired					
	If you have answered yes, please answer the three questions below:					
	(i) When was your central heating system or partial central heating system installed?	About 5 years ago				
	(ii) Do you have a maintenance contract for the central heating system?	No				
	If you have answered yes, please give details of the company with which you have a maintenance contract:					
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).					
8.	Energy Performance Certificate					
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Don't know				
9.	Issues that may have affected your property					
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	No				
	<u>If you have answered yes</u> , is the damage the subject of any outstanding insurance claim?					
b.	Are you aware of the existence of asbestos in your property?	No				
	If you have answered yes, please give details:					

10.	Services							
a.	Please tick which services are connected to your property and give details of the supplier:							
		Services	Connected	Supplier				
		Gas or liquid petroleum gas	1	Utility war	ehouse			
		Water mains or private water supply	1	Scottish w	ater			
		Electricity	1	Utility war	ehouse			
		Mains drainage	<i>✓</i>	Edinburgh	city council			
		Telephone	1	Bt				
		Cable TV or satellite	1	Bt		1		
		Broadband	<ul> <li>✓</li> </ul>	Bt				
b.	Is there a	Is there a septic tank system at your property?						
	<u>If you hav</u>	If you have answered yes, please answer the two questions below:						
	(i) Do you tank?							
	(ii) Do you <u>If you hav</u> you have							
11.	Respons	ibilities for shared or cor	nmon areas					
a.	a. Are you aware of any responsibility to contribute to the cost of anythin used jointly, such as the repair of a shared drive, private road, bound or garden area?				No			
	<u>lf you hav</u>							
b.	Is there a responsibility to contribute to repair and maintenance of the roo common stairwell or other common areas?			ince of the roof,	No			
	<u>lf you hav</u>							

d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	No					
	If you have answered yes, please give details:						
е.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	No					
	If you have answered yes, please give details:						
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	No					
	If you have answered yes, please give details:						
12.	Charges associated with your property						
а.	Is there a factor or property manager for your property?	Yes					
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:						
	Trinity factoring 209/211 brunsfield place Edinburgh EH10 4DH annual payment of £90						
b.	Is there a common buildings insurance policy?	No					
	If you have answered yes, please answer the question below:						
	(i) Is the cost of the insurance included in your monthly/annual factor's charges?						
с.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.						
13.	Specialist works						
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	No					
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.						
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	No					
	If you have answered yes, please give details:						
L	1	1					

с.	If you have answered yesto 13(a) or (b), do you have any guaranteesrelating to this work?If you have answered yes, these guarantees will be needed by thepurchaser and should be given to your solicitor as soon as possible forchecking. If you do not have them yourself <u>please write below who has</u> these documentsand your solicitor or estate agent will arrange for them tobe obtained. You will also need to provide a description of the work carriedout. This may be shown in the original estimate.Guarantees are held by:								
14.	Guarante	ees							
а.	Are there	any g	uarantees or warranties for	r any of t	he followi	ng:			
				No	Yes	Don't know	With title deeds	Lost	
		(i)	Electrical work	1					
		(ii)	Roofing	1					
		(iii)	Central heating	<i>✓</i>					
		(iv)	National House Building Council (NHBC)	1					
		(v)	Damp course	1					
		(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)						
b.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):								
с.	Are there above?	any o	utstanding claims under an	ny of the	guarantee	es listed	No	)	
	If you have answered yes, please give details:								
15.	Boundar	ies							
a.	in the last	10 ye			property	been move	ed No	)	
	<u>If you have</u>	<u>e ans</u>	<u>wered yes</u> , please give detc	ails:					

16.	Notices that affect your property					
	In the past three years have you ever received a notice:					
а.	advising that the owner of a neighbouring property has made a planning application?	No				
b.	that affects your property in some other way?	No				
с.	that requires you to do any maintenance, repairs or improvements to your property?	No				
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate age including any notices which arrive at any time before the date of entry of the purchaser of your property.					

### Declaration by the seller(s)/or other authorised body or persons

I/We confirm that the information is this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

Date:

Before this questionnaire is published into the Home Report a signed copy of this document will have been collected by the selling solicitor. To see a copy of the signed document please contact Black Hay.



8 Manor Place, Edinburgh EH3 7DD 0131 225 7668 edinburgh.residential@hdg.co.uk