# YOUR ONESURVEY HOME REPORT

#### **ADDRESS**

113 James Campbell Road Ayr KA8 0RY

#### PREPARED FOR

Clients of Black Hay

#### INSPECTION CARRIED OUT BY:



#### **SELLING AGENT:**

### Black Hay

HOME REPORT GENERATED BY:



### **Document Index**

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	Ayr - Allied Surveyors Scotland Plc	08/05/2018
Mortgage Certificate	Final	Ayr - Allied Surveyors Scotland Plc	08/05/2018
Property Questionnaire	Final	Clients of Black Hay	04/05/2018
EPC	Final	Ayr - Allied Surveyors Scotland Plc	08/05/2018

#### **Important Notice:**

This report has been prepared for the purposes of and use of Clients of Black Hay. Should your name not be on this report then Onesurvey is unable to guarantee that this is a genuine or complete copy of the Home Report. A personalised copy of this Home Report may be obtained at www.onesurvey.org free of charge.

If you are a potential purchaser of this property you may then present your personalised copy of the report to your advisers or mortgage provider with a view to them requesting a transcription report from the appointed Chartered Surveyor.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes

PART 1

## SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



# Single Survey

## Survey report on:

Surveyor Reference	AD/5320		
Customer	Clients of Black Hay		
Customer address	113 James Campbell Road Ayr KA8 0RY		
Date of Inspection	08/05/2018		
Prepared by	Kevin S Hay, BSc MRICS Ayr - Allied Surveyors Scotland Plc		

#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. <sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\square$ 

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.* 

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

**WARNING**: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

#### 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subject property comprises a mid-terraced house, two	
	storeys in height.	
Accommodation	Ground Floor: Entrance hallway, livingroom, diningroom, kitchen.	
	First Floor: 2 bedrooms, bathroom with wc.	
Gross internal floor area (m2)	85 sq m	
Neighbourhood and location	The property is located in the Craigie district of Ayr. Surrounding properties are of a similar age and style. The property is conveniently located in relation to local facilities and amenities. Ayr Racecourse is located behind the subject property.	
Age	60 yrs or thereby	
Weather	Overcast and dry	
Chimney stacks	Visually inspected with the aid of binoculars where required.	
	The chimney stack is of rendered brick construction and is protected at roof level by lead flashing.	
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where required.	
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.	

	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a	
	3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.	
	The roof is pitched, metal framed and overlaid with concrete tiles. There is a flat copper clad roof over the front window projection which has a painted finish.	
	Access was gained to the roof void through a hatch in the ceiling of the first floor landing.	
Rainwater fittings	Visually inspected with the aid of binoculars where required.	
	Gutters and downpipes are of cast iron construction.	
Main walls	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.	
	The outer walls are of cavity brick construction, rendered externally.	
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.	
	Random windows were opened and closed where possible.	
	Doors and windows were not forced open.	
	The windows are of double glazed replacement type.	
External decorations	Visually inspected.	
	Painted as required.	
Conservatories / porches	N/A	
Communal areas	None apparent.	
Garages and permanent	None.	
outbuildings	There is off-street car parking at the front.	
Outside areas and boundaries	Visually inspected.	

	The same is a stable and discussion of the state of the s		
	There is a slabbed driveway at the front.		
	At the rear, the garden is laid to grass, slabs and shrubs.		
Ceilings	Visually inspected from floor level.		
	The ceilings are understood to be of plasterboard.		
Internal walls	Visually inspected from floor level.		
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.		
	The walls are plasterboard lined.		
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.		
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.		
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.		
	Flooring is of suspended timber construction laid off timber joists. No sub-floor inspection was carried out.		
Internal joinery and	Built-in cupboards were looked into but no stored items were moved.		
kitchen fittings	Kitchen units were visually inspected excluding appliances.		
	The kitchen is fitted with older style units.		
	There is a timber staircase.		
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out.		
	The livingroom houses an older style electric fire.		
Internal decorations	Visually inspected.		
	Decorated as required.		
Cellars	N/A		

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.	
	Mains connected.	
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.	
	Mains connected.	
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.	
	No tests whatsoever were carried out to the system or appliances.	
	Mains connected.	
	The bathroom consists of a wc, washhand basin and bath with electric shower.	
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.	
	No tests whatsoever were carried out to the system or appliances.	
	The gas fired central heating boiler serves panel radiators throughout the property.	
Drainage	Drainage covers etc were not lifted.	
	Neither drains nor drainage systems were tested.	
	Mains connected.	
Fire, smoke and burglar alarms	Visually inspected.	
aidillis	No tests whatsoever were carried out to the system or appliances.	
	There are smoke and burglar alarms in the property. The burglar alarm was turned off at the date of inspection.	


## Any additional limits to inspection

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

At the time of the inspection, the property was unoccupied and partially furnished with fitted floor coverings throughout. It was inspected externally and internally from ground/floor level.

Access was obtained to the roof void although no sub-floor inspection was undertaken.

#### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

#### 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement		
Repair category:		
Notes:	There is evidence of past movement seen in the form of cracking at the external rendering. The movement appears longstanding and there is no obvious evidence of recent deterioration.	

Dampness, rot and infestation		
Repair category:	1	
Notes:	Woodworm damage was noted within the roof void although it is understood that this is to be treated by a firm of timber specialists in the near future and guarantees should be preserved for future reference.	

Chimney stacks	
Repair category:	2
Notes:	General weathering was noted at the chimney head and flashings which would also benefit from being repointed in places.

Roofing including	roof space
Repair category:	2

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Notes:	The roof covering is the original and is showing signs of general weathering. The flat, presumably copper clad, roof over the front window projection will require ongoing maintenance.
	As stated previously, woodworm damage was noted within the roof void although this is to be treated in the near future.
	Old staining was noted at fibreboard sarking panels in the loft area.

Rainwater fittings		
Repair category:	2	
Notes:	Corrosion was noted at cast iron rainwater goods.	

Main walls		
Repair category:	2	
Notes:	A small missing section of render was noted at the front wall adjacent to the front window projection. The walls should be addressed as part of routine, ongoing maintenance.  Cavity wall insulation has been introduced and it is therefore	
	essential that the external walls are maintained in a wind and watertight condition.	

Windows, external doors and joinery		
Repair category:		
Notes:	A defective window seal was noted at one of the bedroom windows. General wear was also noted at operating mechanisms and handles. The windows will require ongoing maintenance.	

Category 3		Category 2	Category 1		
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.		Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.		
	It is understood that the livingroom window was replaced in 2008.				
External decorati	ions				
Repair category:	1				
Notes:	The external appearance of the property is good.				
Conservatories /	porches				
Repair category:					
Notes:	N/A				
Communal areas					
Repair category:					
Notes:	None apparent.				
Garages and permanent outbuildings					
Repair category:					
Notes:	None				

Outside areas and boundaries

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	1
Notes:	The rear garden would benefit from some attention.

Ceilings	
Repair category:	
Notes:	Hairline cracking was noted at ceilings in places which should be repaired as part of routine redecoration.

Internal walls	
Repair category:	1
Notes:	No significant defects were noted at internal walls.

Floors including sub-floors		
Repair category:		
Notes:	Minor "creaking" was noted at flooring adjacent to the front door.	

Internal joinery and kitchen fittings		
Repair category:	2	
Notes:	The kitchen units are dated and would benefit from being replaced.	

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Chimney breasts and fireplaces	
Repair category:	1
Notes:	Moisture meter tests at chimney breasts revealed no evidence of significant dampness at the points of examination. No tests of the electric fire in the livingroom were undertaken.

Internal decorations	
Repair category:	2
Notes:	Aspects of the internal decoration are considered to be dated.

Cellars	
Repair category:	
Notes:	N/A

Electricity		
Repair category:	1	
Notes:	The electrical switchgear is wall mounted in the understair cupboard. It appears it has been upgraded as there are circuit breakers. The electrics should be tested periodically. The current electrical test certification should be exhibited.	

Gas
-----

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	
Notes:	The gas meter box is located at the front elevation of the property.

Water, plumbing and bathroom fittings	
Repair category:	2
Notes:	The bathroom has older style fitments. It is anticipated that an incoming purchaser would install new bathroom fitments.

Heating and hot water	
Repair category:	1
Notes:	The Worcester Green Star 28i Junior combination boiler is wall mounted in the kitchen. This in turn is connected to water filled radiators throughout the property. It is served by a balanced flue and will require annual servicing to remain effective. The current test certification should be exhibited.

Drainage	
Repair category:	
Notes:	Drainage is by gravity feed to the Local Authority sewer. Drainage covers were not lifted nor were any tests undertaken on the system.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	
Communal areas	
Garages and permanent outbuildings	
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	1
Internal decorations	2
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	2
Heating and hot water	1
Drainage	1

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. ACCESSIBILITY INFORMATION

#### **Guidance Notes on Accessibility Information**

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground & First
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES [ ]NO
3. Is there a lift to the main entrance door of the property?	[ ]YES [x]NO
4. Are all door openings greater than 750mm?	[ ]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[ ]YES [x]NO
6. Is there a toilet on the same level as a bedroom?	[x]YES [ ]NO
7. Are all rooms on the same level with no internal steps or stairs?	[ ]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES [ ]NO

#### 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The property is in an area of known former mine workings and it is assumed that there is a satisfactory Coal Report for the subject property.

It is assumed that the property and its value are unaffected by any matters which would or should be revealed to a completing Solicitor by a local search/replies to usual enquiries or by any statutory notice or planning proposal.

#### Estimated re-instatement cost (£) for insurance purposes

150,000

One Hundred and Fifty Thousand Pounds

#### Valuation (£) and market comments

100,000

One Hundred Thousand Pounds

Following a return in confidence to the market, properties are now generally selling well providing mortgage finance remains available and they are realistically priced.

Report author: Kevin S Hay, BSc MRICS				
Company name:	Ayr - Allied Surveyors Scotland Plc			
Address:	3 Alloway Street Ayr KA7 1SP			
Signed:	Electronically Signed: 116079-8E4881DE-282A			
Date of report:	08/05/2018			

P A R T 2.

# MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





	Mortgage Valuation Report							
Property:	113 James Campbell Road Ayr KA8 0RY  Client: Clients of Black Hay Tenure: Ownership							
Date of Inspection:	08/05/2018		Reference: AD/5320					
This report has been prepared as part of your instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising your lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.								
1.0	LOCATION							
	is located in the y located in rela							
2.0	DESCRIPTIO	N		2.1 Age:	60 yrs or there	eby		
The subject p	roperty comprise	es a mid-terrace	ed house, two s	toreys in height			-	
3.0	CONSTRUCT	ION						
	brick constructid and tiled with a			front window pr	ojection.			
4.0	ACCOMMOD	ATION						
Ground Floor	: Entrance hallw	ay, livingroom,	diningroom, kito	hen.				
First Floor: 2	bedrooms, bathr	oom with wc.						
5.0	SERVICES (N	lo tests have b	een applied to	any of the se	rvices)			
Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains	
Central Heat	ing:	Full gas						
6.0	OUTBUILDIN	OUTBUILDINGS						

Garage:		Off-street car parking				
Others:		-				
7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
The property v	vould benefit fro	om a scheme of	modernisation	and redecoration as kitchen ar	nd bathroom fitn	nents are
				we have been informed that the department of the preserved for future reference.		ed by a firm
		vement seen in obvious evidenc		cking at the external rendering. erioration.	The movement	t appears
There are also	a few minor m	atters which sho	ould be capable	of remedy by routine mainten	ance.	
8.0	ESSENTIAL I property)	REPAIR WORK	(as a condition	n of any mortgage or, to preser	ve the condition	of the
None apparent.						
8.1 Retention	recommended	d:	N/A			
9.0	ROADS &FO	OTPATHS				
Made up and adopted.						
Made up and a	adopted.					
Made up and a	BUILDINGS I	NSURANCE	150,000	GROSS EXTERNAL FLOOR AREA	98	Square metres
	BUILDINGS I (£): This figure is a should be insu property in its allowance has	an opinion of an ired against tota existing design been included been made for	appropriate sul al destruction or and materials for inflation dur		ubstantial outbu ning reconstruct ot been include ning re-construct	metres uildings ion of the id. No tion and no
	BUILDINGS I (£): This figure is a should be insu property in its allowance has allowance has	an opinion of an ured against tota existing design a been included a been made for vised.	appropriate sul al destruction or and materials for inflation dur	FLOOR AREA  m for which the property and so a re-instatement basis assum Furnishings and fittings have no ing the insurance period or dur	ubstantial outbu ning reconstruct ot been include ning re-construct	metres uildings ion of the id. No tion and no
10.0	BUILDINGS I (£):  This figure is a should be insupproperty in its allowance has insurers is adv.  GENERAL RI s in an area of k	an opinion of an ured against tota existing design been included been made for vised.	appropriate sulal destruction or and materials. for inflation dur. VAT, other tha	FLOOR AREA  m for which the property and so a re-instatement basis assum Furnishings and fittings have no ing the insurance period or dur	ubstantial outbu ning reconstruct ot been include ring re-construct discussions wi	metres  uildings ion of the id. No tion and no th your
11.0  The property is the subject pro-	BUILDINGS I (£):  This figure is a should be insurproperty in its allowance has allowance has insurers is adv.  GENERAL RI Is in an area of keeperty.	an opinion of an ured against total existing design is been included been made for vised.  EMARKS  Known former may and its value a	appropriate sural destruction or and materials. for inflation durity VAT, other that ine workings are unaffected by	FLOOR AREA  m for which the property and so a re-instatement basis assum Furnishings and fittings have noting the insurance period or during non professional fees. Further	ubstantial outbuing reconstruct ot been include ing re-construct discussions wi	metres  uildings ion of the id. No tion and no ith your  al Report for
11.0  The property is the subject pro-	BUILDINGS I (£):  This figure is a should be insured property in its allowance has insurers is advised GENERAL RI Is in an area of known and the property.  That the property is in an area of known and the property in its allowance has insurers is advised in an area of known and the property.  That the property is in an area of known and investigation of investigation of matters to be asbestos in or beyond the solution.	an opinion of an ared against total existing design is been included is been made for vised.  EMARKS  Anown former made is search/replies  On the assumpting proposals, of any contamination outwith the scope of this inspectors.	appropriate sural destruction or and materials. for inflation durity VAT, other that the workings are unaffected by the usual enquirition of vacant ponerous burden ation on, under the components of this reports components of ection to test for all destruction of the test for ection to test for all destruction or the test for all destruction or all destructions or all destruction or all destruction or all destruction or all destructions or all destructi	FLOOR AREA  m for which the property and so a re-instatement basis assumed the insurance period or during the insurance peri	ubstantial outbuing reconstruct of been include ing re-construct discussions will satisfactory Coastisfactory C	metres  uildings ion of the id. No tion and no th your  al Report for aled to a osal.  by any umed that all d obtained. No consider such contain est. It is lvised that if
11.0  The property is the subject proof it is assumed to completing So	BUILDINGS I (£):  This figure is a should be insured property in its allowance has insurers is advised GENERAL RI Is in an area of known and the property.  That the property is in an area of known and the property in its allowance has insurers is advised in an area of known and the property.  That the property is in an area of known and investigation of investigation of matters to be asbestos in or beyond the solution.	an opinion of an ared against total existing design is been included is been made for vised.  EMARKS  Known former made is search/replies  On the assumpting proposals, of any contaminal outwith the scope of this inspection of the inspection of th	appropriate sural destruction or and materials. for inflation durity VAT, other that the workings are unaffected by the usual enquirition of vacant ponerous burden ation on, under the components of this reports components of ection to test for all destruction of the test for ection to test for all destruction or the test for all destruction or all destructions or all destruction or all destruction or all destruction or all destructions or all destructi	m for which the property and so a re-instatement basis assume Furnishings and fittings have noting the insurance period or during the insurance period or during on professional fees. Further and it is assumed that there is a solution or by any statutory notice of the sor by any statutory notice of the sor by any statutory notice of the sor within the property has been or within the property has been as a state of the sor within the property has been as a state of the sor within the property built prior to the sor as a state of the sor as a stat	ubstantial outbuing reconstruct of been include ing re-construct discussions with a satisfactory Coastal should be revear planning property is unaffected in its assument and as we discussion and as well as a discussion and as well as wel	metres  uildings ion of the id. No tion and no th your  al Report for aled to a osal.  by any umed that all d obtained. No consider such contain est. It is lvised that if
11.0  The property is the subject product of	BUILDINGS I (£):  This figure is a should be insured property in its allowance has allowance has insurers is adv.  GENERAL RI Is in an area of keeperty.  That the property in its allowance has insurers is adv.  GENERAL RI Is in an area of keeperty.  That the property in its allowance has insurers is adv.  VALUATION adverse plant necessary Loc investigation of matters to be asbestos in or beyond the so they have any.  Market Value	an opinion of an ared against total existing design is been included is been made for vised.  EMARKS  Anown former made is search/replies  On the assumpting proposals, of any contamination outwith the scope of this inspector concerns then in present:	appropriate sural destruction or and materials. for inflation durity VAT, other that the workings are unaffected by the sural enquirition of vacant properties, which mation on, under the components of they should as the should as the struction of the structure.	respectively and statement basis assume for which the property and statement basis assume furnishings and fittings have not ing the insurance period or duration on professional fees. Further and it is assumed that there is a set of any matters which would or sees or by any statutory notice of the set of the	ubstantial outbuing reconstruct of been include ing re-construct discussions with a satisfactory Coastal should be revear planning property is unaffected in its assument and as we discussion and as well as a discussion and as well as wel	metres  uildings ion of the id. No tion and no th your  al Report for aled to a osal.  by any umed that all d obtained. No consider such contain est. It is lvised that if

	completion of works (£):	of essential				
12.3 Suitable security for normal mortgage purposes?		Yes				
12.4	Date of Valua	ation:	04/05/2018			
Signature:		Electronically	ally Signed: 116079-8E4881DE-282A			
Surveyor:	Kevin S Hay		BSc MRICS		Date:	08/05/2018
Ayr - All	Ayr - Allied Surveyors Scotland Plc					
Office: 3 Alloway Street Ayr KA7 1SP				Tel: 01292 260 509 Fax: 01292 610 645 email: ayr@alliedsurveyors	sscotland.com	

PART 3.

# ENERGY REPORT

A report on the energy efficiency of the property.



# energy report

## energy report on:

Property address	113 James Campbell Road Ayr KA8 0RY
Customer	Clients of Black Hay
Customer address	113 James Campbell Road Ayr KA8 0RY
Prepared by	Kevin S Hay, BSc MRICS Ayr - Allied Surveyors Scotland Plc

### **Energy Performance Certificate (EPC)**

**Dwellings** 

**Scotland** 

#### 113 JAMES CAMPBELL ROAD, AYR, KA8 0RY

Dwelling type: Mid-terrace house
Date of assessment: 04 May 2018
Date of certificate: 08 May 2018
Total floor area: 86 m²

Total floor area: 86 m<sup>2</sup>

Primary Energy Indicator: 225 kWh/m²/year

**Reference number:** 0018-8225-7100-0444-0906 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


aas

#### You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,427	See your recommendations
Over 3 years you could save*	£285	report for more information

<sup>\*</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide ( $CO_2$ ) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (66)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Floor insulation (suspended floor)	£800 - £1,200	£180.00	<b>⊘</b>
2 Solar water heating	£4,000 - £6,000	£105.00	$\bigcirc$
3 Solar photovoltaic (PV) panels	£5,000 - £8,000	£852.00	<b>⊘</b>

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity	***	★★★☆☆
Roof	Pitched, 250 mm loft insulation	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully double glazed	***	★★★☆☆
Main heating	Boiler and radiators, mains gas	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Secondary heating	Room heaters, electric	_	_
Hot water	From main system	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Lighting	Low energy lighting in all fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 39 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.4 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,926 over 3 years	£1,746 over 3 years	
Hot water	£324 over 3 years	£219 over 3 years	You could
Lighting	£177 over 3 years	£177 over 3 years	save £285
Totals	£2,427	£2,142	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after	Green	
		Indicative cost	per year	Energy	Environment	Deal
1	Floor insulation (suspended floor)	£800 - £1,200	£60	C 70	C 69	
2	Solar water heating	£4,000 - £6,000	£35	C 71	C 71	
3	Solar photovoltaic panels, 2.5 kWp	£5,000 - £8,000	£284	B 81	C 80	<b>©</b>

Measures which have a green deal tick or are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

#### Choosing the right improvement package

**energy**° saving trust

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

Page 33 Page 2 of 5

#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### 2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### 3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	8,935	N/A	N/A	N/A
Water heating (kWh per year)	2,158			

Page 34 Page 3 of 5

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Kevin Hay
Assessor membership number: EES/008225

Company name/trading name: Allied Surveyors Scotland Plc

Address: 3 Alloway Street

Ayr

KÁ7 1SP Phone number: 01292 260509

Email address: ayr@alliedsurveyors.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Page 35 Page 4 of 5

#### Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.

Authorised home energy assessment

Finance at no upfront cost

Choose from authorised installers May be paid from savings in energy bills

Repayments stay with the electricity bill payer

Page 36 Page 5 of 5

P A R T 4.

## PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



## **Property Questionnaire**

Property Address	113 James Campbell Road Ayr KA8 0RY	
Seller(s)	Clients of Black Hay	
Completion date of property questionnaire	04/05/2018	

Note for sellers

1.	Length of ownership	
	How long have you owned the p September 1981	property?
2.	Council tax	
	Which Council Tax band is your [ ]A [ ]B [x]C [ ]D [ ]E [ ]F [ ]G [ ]H	
3.	Parking	
	What are the arrangements for particle (Please tick all that apply)	parking at your property?
	Garage	[]
	Allocated parking space	[]
	Driveway	[x]
	Shared parking	[]
	On street	[]
	Resident permit	[]
	Metered parking	[]
	Other (please specify):	

	Conservation area
--	-------------------

4.		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	[ ]YES [x]NO [ ]Don't know
5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	[ ]YES [x]NO
6.	Alterations/additions/extensions	
а	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	[ ]YES [x]NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	[]YES[]NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	[x]YES [ ]NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	[x]YES [ ]NO
	(ii) Did this work involve any changes to the window or door openings?	[]YES [x]NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	

7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	[x]YES [ ]NO [ ]Partial
	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).  Gas fired	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?  Within the last 10 years	
	(ii) Do you have a maintenance contract for the central heating system?	[x]YES [ ]NO
	If you have answered yes, please give details of the company with which you have a maintenance contract  British Gas	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).  Annually	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES [ ]NO
9.	Issues that may have affected your property	
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[ ]YES [x]NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES[]NO
b	Are you aware of the existence of asbestos in your property?	[ ]YES [x]NO
	If you have answered yes, please give details:	
10.	Services	

а	Please tick which services are connected to your property and give details of the supplier:		
	Services	Connected	Supplier
	Gas or liquid petroleum gas	Υ	
	Water mains or private water supply	Υ	
	Electricity	Υ	
	Mains drainage	Υ	
	Telephone	Υ	Talk Talk
	Cable TV or satellite	N	
	Broadband	N	
b	Is there a septic tank system at your property?		[ ]YES [x]NO
	If you have answered yes, please answer the two below:	questions	
	(i) Do you have appropriate consents for the disc your septic tank?	harge from	[ ]YES [ ]NO [ ]Don't know
	(ii) Do you have a maintenance contract for your	septic tank?	[]YES[]NO
	If you have answered yes, please give details of with which you have a maintenance contract:	the company	
11.	Responsibilities for shared or common areas		
а	Are you aware of any responsibility to contribute anything used jointly, such as the repair of a sharprivate road, boundary, or garden area?  If you have answered yes, please give details:		[ ]YES [x]NO [ ]Don't know
b	Is there a responsibility to contribute to repair and of the roof, common stairwell or other common a lf you have answered yes, please give details:		[ ]YES [x]NO [ ]N/A
С	Has there been any major repair or replacement the roof during the time you have owned the prop		[ ]YES [x]NO
d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries?  [x]YES []NO lf you have answered yes, please give details:		[x]YES [ ]NO
	The path at 115 James Campbell Road is used to	o put out bins.	

е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?  If you have answered yes, please give details:	[ ]YES [x]NO
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.)  If you have answered yes, please give details:	[ ]YES [x]NO
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[ ]YES [x]NO
b	Is there a common buildings insurance policy?	[ ]YES [x]NO [ ]Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
С	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[ ]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they	[]YES [x]NO
b	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.  As far as you are aware, has any preventative work for dry rot,	[]YES [x]NO
b	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.  As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.  As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?  If you have answered yes, please give details:  If you have answered yes to 13(a) or (b), do you have any	

be shown in the original estimate. Guarantees are held by:

14.	Guarantees	
а	Are there any guarantees or warranties for any of the following:	
(i)	Electrical work	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
(ii)	Roofing	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
(iii)	Central heating	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
(iv)	National House Building Council(NHBC)	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
(v)	Damp course	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	[x]NO [ ]YES [ ]Don't know [ ]With title deeds [ ]Lost
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):	
С	Are there any outstanding claims under any of the guarantees listed above?	[]YES [x]NO
	If you have answered yes, please give details:	

15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years?	[ ]YES [x]NO [ ]Don't know
	If you have answered yes, please give details:	
16.	Notices that affect your property	
In the	In the past three years have you ever received a notice:	
а	advising that the owner of a neighbouring property has made a planning application?	[x]YES [ ]NO

## property questionnaire

b	that affects your property in some other way?	[ ]YES [x]NO
С	that requires you to do any maintenance, repairs or improvements to your property?	[ ]YES [x]NO
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.	
Signature(s):	Robert Lumsden
Capacity:	[ ]Owner [x]Legally Appointed Agent for Owner
Date: 04/05/2018	