YOUR ONESURVEY HOME REPORT

ADDRESS

Flat Upper Left 10 Virginia Gardens AYR KA8 8JE

PREPARED FOR

Client of Black Hay

INSPECTION CARRIED OUT BY:



SELLING AGENT:

Black Hay

HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Index of Documents			
Single Survey	Final	D M Hall - Ayr	28/03/2022
Mortgage Certificate	Final	D M Hall - Ayr	28/03/2022
Property Questionnaire	Final	Client of Black Hay	19/04/2022
EPC	Final	D M Hall - Ayr	28/03/2022

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is essential that you visit www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1

SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	YR220354
Customer	Client of Black Hay
Selling address	Flat Upper Left 10 Virginia Gardens AYR KA8 8JE
Date of Inspection	25/03/2022
Prepared by	Mark Rutherford, MA (hons) MRICS D M Hall - Ayr

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\Delta}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller:
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 <u>Category 1</u>: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

_		
Description	The subjects comprise a purpose built first floor left hand flat situated within a two storey end-terraced building which contains four flats. There is a shared entrance.	
Accommodation	FIRST FLOOR:- Entrance Hallway, Lounge, Kitchen, Two Bedrooms, Bathroom.	
Gross internal floor area (m2)	66 square metres.	
Neighbourhood and location	The property is situated within a mixed residential and commercial location where surrounding properties are of a similar age and type. Local amenities are readily available.	
Age	Approximately 120 years.	
Weather	Dry and sunny following a recent period of settled weather conditions.	
Chimney stacks	Visually inspected with the aid of binoculars where required.	
	Brick construction with a pointed and render finish. The adjacent flashings are formed in lead.	
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where required. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Flat roofs have a limited life and depending on their age and quality of workmanship can fail at any time.	

	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.	
	The roof is pitched and overlaid with slates.	
	I was able to partially inspect the roof space and gained access from the hatch above the common landing. The roof is built of timber trusses and boarded over with timber sarking. Insulation material is laid between and over the ceiling joists.	
Rainwater fittings	Visually inspected with the aid of binoculars where required.	
	Rainwater units are of PVC material consisting of half round and ogee style gutters discharging into round downpipes.	
Main walls	Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected.	
	The outer walls are of solid stone and solid brick construction, having a pointed and render finish. A dampproof course is not visible and it is unclear whether a building of this age would have a damp-proof membrane incorporated within the external walls. There are sub-floor ventilators to lower walls.	
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open.	
	Windows are of uPVC double glazed type. The external doors leading to and from the shared entrance are of timber design and the external door leading to the subject flat is of uPVC design.	
External decorations	Visually inspected.	
	External decoration has a painted finish.	
Conservatories / porches	None.	
Communal areas	Circulation areas visually inspected.	

	Entry to each flat in the building is via a shared entrance. There is a secure door entry system.	
Garages and	Visually inspected.	
permanent outbuildings	There is a brick outbuilding, which I have assumed to be communal.	
Outside areas and boundaries	Visually inspected.	
boundaries	There are garden grounds to the rear of the property which I have assumed to be communal, these being laid out in grass and concrete paving. Boundary divisions are marked by brick walls.	
Ceilings	Visually inspected from floor level.	
	Ceilings are of lath and plaster materials.	
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate.	
	Internal walls are of masonry construction finished in plaster. There are tiled wall finishes to the kitchen and bathroom.	
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch. Visible flooring is of suspended timber construction consisting of tongue and groove boards laid over timber is interpretable.	
Internal joins and	joists.	
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved. Kitchen units were visually inspected excluding appliances.	
	Internal joinery is of timber and there are timber internal doors. The kitchen contains floor and wall mounted storage units.	

	1	
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out.	
	Any original fireplaces have been removed in the past.	
Internal decorations	Visually inspected.	
	Internal decorative finishes are generally papered or painted.	
Cellars	None.	
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.	
	Mains supply. The electrical consumer unit is located within the entrance hallway.	
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.	
	Mains supply. The gas meter is located in an external meter box.	
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.	
	Mains water supply. Visible sections of pipework are of copper and PVC materials. Sanitary fittings in the bathroom comprise a white suite with low level WC, wash hand basin and bath. There is a stainless steel sink unit within the kitchen.	
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.	

	There is an "Ideal" wall mounted gas heating boiler situated within a bedroom. This serves water filled steel panelled radiators throughout and it also provides domestic hot water.	
Drainage	Drainage covers etc were not lifted. Neither drains nor drainage systems were tested.	
	Drainage is to the main sewerage system.	
Fire, smoke and burglar alarms	Visually inspected.	
aiaiiiis	No tests whatsoever were carried out to the system or appliances.	
	There are smoke and carbon monoxide alarms installed.	
	Legislation by the Scottish Government, which took effect from February 2022, requires residential properties to have a system of inter-linked smoke alarms, carbon monoxide detectors and heat detectors. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.	
Any additional limits to inspection	Only the subject flat and internal communal areas giving access to the flat were inspected.	
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.	
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.	
	Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.	
	I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.	
	The report does not include an asbestos inspection. However asbestos was widely used in the building industry	

until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and you have concerns you should engage a qualified asbestos surveyor.

Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.

The property was unoccupied, although furnished and floors were covered. Floor coverings restricted my inspection of flooring. I was unable to inspect the sub-floor area.

Personal effects in cupboards and fitted wardrobes were not moved and restricted my inspection.


My physical inspection of the common roof void area was restricted due to insulation material and lack of suitable crawl boards. As a result the roof void area was only viewed from the access hatch.

Concealed areas beneath and around bath/shower trays were not visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.

The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.

Where repairs are required at height compliance with Health and Safety legislation often requires the use of scaffolding which can significantly impact on the cost of repair. Pricing repairs is out with the remit of this report but it would be prudent to consider costs and budgeting before offering. The various trades can advise further.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the following 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement		
Repair category:		
Notes:	The property has been affected by previous movement but within the limitations of the inspection there was no evidence to suggest that this is ongoing.	

Dampness, rot and infestation		
Repair category:	2	
Notes:	Elevated moisture readings and timber decay were noted adjacent to a cupboard within a bedroom.	

Chimney stacks		
Repair category:	2	
Notes:	No significant defects noted, however, chimneys, particularly of older properties, can be a source of water penetration and defects to rendering, mortar and flashings can be difficult to detect from a ground level inspection. These will require to be maintained in good repair to discourage water penetration. It is good practice to engage a reputable roofing or building contractor prior to purchase to advise on life expectancy and repair/replacement costs.	

Roofing including roof space

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Repair category:	2
Notes:	There are a number of broken and loose slates together with staining to roof timbers. A reputable roofing contractor can be asked to inspect the roof structure to advise on all necessary repairs to ensure wind and water tightness. Inspection at close quarters may reveal further deterioration/damage to roofing materials, especially where these are original. Regular maintenance is anticipated until replacement.

Rainwater fittings	
Repair category:	
Notes:	No significant defects evident.

Main walls	
Repair category:	2
Notes:	Erosion and open pointing is noted to the stonework and brickwork of external walls.

Windows, external doors and joinery	
Repair category:	1
Notes:	No significant defects evident.
	Windows units/access doors have been replaced in the past. Random windows and doors are opened but not all and inspections can be restricted by window blinds, curtains, ornaments etc. Handles, locks and opening mechanisms can deteriorate through

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

usage and repair or replacement can be anticipated on an ad hoc basis. No assurances can be provided that all window fitments are
functional.

External decorations	
Repair category:	2
Notes:	Outside paintwork has deteriorated and redecoration is now required. Regular re-painting of external joinery will prolong its life span.

Conservatories / porches	
Repair category:	
Notes:	None.

Communal areas	
Repair category:	2
Notes:	Deterioration is noted to the plaster finishes within the common close and stairwell areas.

Garages and permanent outbuildings	
Repair category:	2
Notes:	The common outbuilding requires general repair.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Outside areas and boundaries	
Repair category:	2
Notes:	Garden walls have deteriorated and require general repair.
	Concrete hard-standing areas are damaged and repairs are required.

Ceilings	
Repair category:	2
Notes:	Cracked and damaged plaster finishes require repair.
	The textured finishes may contain asbestos based material. See information on Asbestos in the Limitations of Inspection section above.

Internal walls	
Repair category:	
Notes:	No significant defects evident.

Floors including sub-floors	
Repair category:	
Notes:	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Sections of flooring are loose/uneven.

Internal joinery and kitchen fittings	
Repair category:	2
Notes:	Deterioration is noted to the kitchen units, work surfaces and areas of internal joinery.
	Also see section: "Dampness, Rot and Infestation."

Chimney breasts and fireplaces	
Repair category:	1
Notes:	Where fireplaces have been removed there is limited provision for ventilation. Unventilated chimney breasts can result in condensation. Disused chimneys should be capped and vented.

Internal decorations	
Repair category:	2
Notes:	Decorative finishes are marked.

Cellars	
Repair category:	
Notes:	None.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Electricity	
Repair category:	2
Notes:	It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IEE regulations. The electrical installation is dated as the electrical sockets are of an older design and are mounted on timber skirting boards. Further advice will be available from a NICEIC/SELECT registered electrician.

Gas	
Repair category:	1
Notes:	Trade bodies governing gas installations currently advise that gas appliances should be tested prior to change in occupancy and thereafter at least once a year by a Gas Safe registered contractor. It is assumed that gas appliances comply with relevant regulations.

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	Seals around bath and shower areas are frequently troublesome and require regular maintenance. Failure to seals can result in dampness/decay within hidden areas of the property.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Heating and hot water		
Repair category:	1	
Notes:	It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations.	
	Boilers and central heating systems should be tested and serviced by a Gas Safe registered contractor on an annual basis to ensure their safe and efficient operation.	
	The radiators are of an older type and the casing to the boiler is loose. A Gas Safe registered contractor can advise further.	

Drainage	
Repair category:	
Notes:	No significant defects evident.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information

Structural movement	1
Dampness, rot and infestation	2
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	1
External decorations	2
Conservatories / porches	
Communal areas	2
Garages and permanent outbuildings	2
Outside areas and boundaries	2
Ceilings	2
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	1
Internal decorations	2
Cellars	
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	First
2. Are there three steps or fewer to a main entrance door of the property?	[]YES [x]NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[x]YES []NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.

The Building factor should be asked to confirm that there are no planned or outstanding repair schemes for the building containing the flat. The flat may have a common building reinstatement policy.

The subjects form part of a tenement/block of flats and it has been assumed that maintenance/repair costs of the common parts of the building will be shared on an equitable basis with adjoining proprietors. It is therefore assumed that the cost of common repairs detailed within the report will be apportioned accordingly although exact liability should be confirmed.

Estimated re-instatement cost (£) for insurance purposes

250,000

TWO HUNDRED AND FIFTY THOUSAND POUNDS. It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

Valuation (£) and market comments

70.000

SEVENTY THOUSAND POUNDS.

Report author:	Mark Rutherford, MA (hons) MRICS	
Company name:	D M Hall - Ayr	
Address:	15 Miller Road Ayr KA7 2AX	
Signed:	Electronically Signed: 202730-BD44622C-40C8	
Date of report:	28/03/2022	

P A R T 2.

MORTGAGE VALUATION REPORT

Includes a market valuation of the property.





Mortgage Valuation Report Flat Upper Left Client: Client of Black Hay Property: 10 Virginia Gardens Tenure: Absolute Ownership. **AYR** KA8 8JE 25/03/2022 Date of Reference: YR220354 Inspection: This report has been prepared as part of your instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising your lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation - Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor. 1.0 **LOCATION** The property is situated within a mixed residential and commercial location where surrounding properties are of a similar age and type. Local amenities are readily available. 2.0 **DESCRIPTION** 2.1 Age: Approximately 120 years. The subjects comprise a purpose built first floor left hand flat situated within a two storey end-terraced building which contains four flats. There is a shared entrance. 3.0 CONSTRUCTION The outer walls are of solid stone and solid brick construction. The roof is pitched and overlaid with slates. 4.0 **ACCOMMODATION** FIRST FLOOR:- Entrance Hallway, Lounge, Kitchen, Two Bedrooms, Bathroom. SERVICES (No tests have been applied to any of the services) 5.0 Water: Mains **Electricity:** Gas: Mains Mains Drainage: Mains **Central Heating:** Gas fired boiler to radiators **OUTBUILDINGS** 6.0 Garage: None. Others: Communal brick outbuilding.

7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
				ough requiring a degree of up gnificant defects which would a		
8.0	ESSENTIAL R property)	EPAIR WORK	(as a condition	of any mortgage or, to preser	ve the condition	of the
None.						
8.1 Retention	recommended	•	None.			
9.0	ROADS &FOC	TPATHS				
Made up and	adopted.					
10.0	BUILDINGS IN (£):	ISURANCE	250,000	GROSS EXTERNAL FLOOR AREA	77	Square metres
	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.					
11.0	GENERAL RE	MARKS				
When inspect	ed, the property v	was unoccupie	d, although furn	ished and floors were covered	l.	
12.0	2.0 VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.					
12.1	Market Value in present condition (£):		70,000	SEVENTY THOUSAND POUNDS		
12.2	Market Value on completion of essential works (£):					
12.3	Suitable security for normal mortgage purposes?					
12.4	Date of Valuat	f Valuation: 25/03/2022				
Signature:	Signature: Electronically Signed: 202730-BD44622C-40C8					
Surveyor:	Mark Rutherford MA (hons) MRICS Date: 28/03/2022			28/03/2022		
D M Hall - Ayr						

Office:


15 Miller Road
Ayr
Fax:
KA7 2AX

Tel: 01292 286974
Fax:
email: ayr@dmhall.co.uk,margaret.gray@dmhall.co.uk

P A R T 3 .

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	Flat Upper Left 10 Virginia Gardens AYR KA8 8JE
,	
Customer	Client of Black Hay
Customer address	Flat Upper Left 10 Virginia Gardens AYR KA8 8JE
Prepared by	Mark Rutherford, MA (hons) MRICS D M Hall - Ayr

Energy Performance Certificate (EPC)

Dwellings

Scotland

FIRST FLOOR LEFT, 10 VIRGINIA GARDENS, AYR, KA8 8JE

Dwelling type:Top-floor flatDate of assessment:25 March 2022Date of certificate:25 March 2022

Total floor area: 66 m²

Primary Energy Indicator: 242 kWh/m²/year

Reference number: 7812-4127-5000-0935-0222 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£1,881	See your recommendations
Over 3 years you could save*	£516	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (66)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	
1 Internal or external wall insulation	£4,000 - £14,000	£516.00	

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	****	***
	Solid brick, as built, no insulation (assumed)	****	***
Roof	Pitched, 200 mm loft insulation	****	★★★★ ☆
Floor	(another dwelling below)	_	_
Windows	Fully double glazed	****	★★★ ☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★ ☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	***
Secondary heating	None	_	_
Hot water	From main system	★★★★☆	★★★ ☆
Lighting	Low energy lighting in 83% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 43 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.0 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,419 over 3 years	£900 over 3 years	
Hot water	£255 over 3 years	£258 over 3 years	You could
Lighting	£207 over 3 years	£207 over 3 years	save £516
Total	s £1,881	£1,365	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

December ded mass	nmended measures	lu disetiva sest	Typical saving	Rating after improvement		
Recommended mea	sures	Indicative cost	per year	Energy	Environment	
1 Internal or extern	al wall insulation	£4,000 - £14,000	£172	C 77	C 78	

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,698	N/A	N/A	(3,921)
Water heating (kWh per year)	1,946			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Mark Rutherford

Assessor membership number: EES/009464

Company name/trading name: D M Hall Chartered Surveyors LLP

Address: 15 Miller Road

Ayr KA7 2AX

Phone number: 0131 477 6000
Email address: dmhall@dmhall.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



PART 4.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Address:

10 VIRGINIA GARDENS

AYR

Seller/s: ROBERT HAIMILTON

Completion date of Property Questionnaire:

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

	Longly of our angles		
1	Length of ownership		
	How long have you owned the property?	years	
2	Council Tax		
	Which Council tax band is your property in?	Kno	ron
3	Parking (tick all applicable)		
	☐ Garage ☐ Allocated Parking Space ☐ Driveway ☐ Shared Parking ☐ On Street ☐ Resident Permit ☐ Metered Parking ☐ Other (Please specify)		
4	Conservation area		
-	Conservation area	Yes	
	Is your property in a designated Conservation area (that	No	
	is an area of special architectural or historical interest,	Unknown	
	the character or appearance of which it is desirable to preserve or enhance)?		

5	Listed buildings		
		Yes	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special	No	1/
	architectural or historical interest)?	Unknown	
6	Alterations/additions/extensions		
a (i)	During your time in the property, have you carried out any structural alterations, additions or extensions (for example,	Yes	
	provision of an extra bath/shower room, toilet or bedroom)?	No	1
	If you have answered Yes, please describe below the changes which you have made:	Unknown	
(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes No Unknown	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes	
]		No	A
	If you have answered Yes, please answer the 3 questions below:	Unknown	
(i)	Were the replacements the same shape and type as the ones you replaced?	Yes	
		No	V
		Unknown	
(ii)	Did this work involve any changes to the window or door openings?	Yes	
	openings:	No	V
		Unknown	
(iii)	Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicitor or estate agent.		

7	Central heating		
а	Is there a central heating system in your property?	Yes	â
	(Note: a partial central heating system is one which does not heat	No	
	all the main rooms of the property – the main living room, the	Partial	
	bedroom/s, the hall and the bathroom)	Unknown	
	If you have answered Yes or Partial – what kind of central heating is there?		
	(Examples: gas-fired, solid fuel, electric storage heating, gas, warm air).	GAS	Ŝ
	If you have answered Yes, please answer the 3 questions below:		
(i)	When was your central heating system or partial central heating sys	stem installed?	
(ii)	Do you have a maintenance contract for the central heating	Yes	
	system?	No Unknown	
	If yes, please give details of the company with which you have a	Unknown	
	maintenance contract:		
(iii)	When was your maintenance agreement last renewed? (please prov year)	vide the month	and
8	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old? (PLEASE NOTE: Please tick 'YES' as the surveyor will complete this at the time of inspection)	Yes	>
9	Issues that may have affected your property		
a	Has there been any storm, flood, fire or other structural damage	Yes	
	to your property while you have owned it?	No	1
		Unknown	
	If you have answered Yes, is the damage the subject of any	Yes	
	outstanding insurance claim?	No	
b	Are you aware of the existence of asbestos in your property?	Yes	
	If you have answered Yes, please give details:	No Unknown	
	1. , 2 and anterior can real product give detailer	CHAILOANI	

10	Services				
а	Please tick which services	s are connecte	ed to your property and give deta	ails of the supp	lier
Serv	ices	Connected	Supplier		
Gas	or liquid petroleum gas	GAS			
Wate supp	er mains or private water ly	MAINS WATER			
Elect	ricity	V 35			
Main	s drainage	4125			
Telep	phone	NO			
Cabl	e TV or satellite				
Broa	dband	NO			
b	Is there a septic tank sys	tem at your p	roperty?	Yes	
				No	
				Unknown	iß
			ver the 2 questions below:		
(i)	Do you have appropriate tank?	consents for t	the discharge from your septic	Yes No	
				Unknown	
(ii)	Do you have a maintena	nce contract fo	or your septic tank?	Yes	
```	,		, , , , , , , , , , , , , , , , , , ,	No	
	If you have answered Ye which you have a mainte		details of the company with t:		•

11	Responsibilities for shared or common areas		
а	Are you aware of any responsibility to contribute to the cost of	Yes	
	anything used jointly, such as the repair of a shared drive,	No	
	private road, boundary, or garden area?	Unknown	
	If you have answered Yes, please give details:		
b	Is there a responsibility to contribute to repair and maintenance	Yes	
	of the roof, common stairwell or other common areas?	No	
	,	Unknown	
	If you have answered yes, please give details:	N/A	
С	Has there been any major repair or replacement to any part of	Yes	
	the roof during the time you have owned the property?	No	1
1		Unknown	
d	Do you have the right to walk over any of your neighbours'	Yes	1/
١	property – for example to put out your rubbish bin or maintain	No	
	your boundaries?	Unknown	
	If you have answered Yes, please give details:		
e	As far as you are aware, do any of your neighbours have the	Yes	1,/
١٠	right to walk over your property, for example to put out their	No	19
ĺ	rubbish bin or to maintain their boundaries?	Unknown	
	The state of the s	Olikilovii	
	If you have answered Yes, please give details:		
f	As far as you are aware, is there a public right of way across any	Yes	
	part of your property? (public right of way is a way over which	No	W
	the public has a right to pass, whether or not the land is privately owned.)	Unknown	
	If you have answered Yes, please give details:		
12	Charges associated with your property		·
a	Is there a factor or property manager for your property?	Yes	
-	as areas a reason or property, manager for your property.	No	17
	If you have answered Yes, please provide the name and address,	Unknown	
	and give details of any deposit held and approximate charges:		

b	Is there a common buildings insurance policy?	Yes	1/
		No	
		Unknown	
	If you have answered Yes, is the cost of the insurance included in		
	your monthly/annual factor's charges?	Yes	
		No	11
		Unknown	
С	Please give details of any other charges you have to pay on a regu		
:	upkeep of common areas or repair works, for example to a residen maintenance or stair fund.	ts' association,	or
13	Specialist works		
а	As far as you are aware, has treatment of dry rot, wet rot, damp	Yes	
	or any other specialist work ever been carried out to your	No	V
	property?	Unknown	
	<u> </u>		
	If you have answered Yes, please say what the repairs were for,		
	whether you carried out the repairs (and when) or if they were		
	done before you bought the property:	1	
b	As far as you are aware, has any preventative work for dry rot,	Yes	1
	wet rot or damp ever been carried out to your property?	No	
1	,	Unknown	1/
	If you have answered Yes, please give details:		<u> </u>
	• • •		
	The same base and same of the		1
С	If you have answered Yes to 13(a) or 13(b), do you have any guarantees relating to this work?	Yes	<u> </u>
		No	
	If you have answered Yes, these guarantees will be needed by	Unknown	
	the purchaser and should be given to your solicitor as soon as		
	possible for checking. If you do not have them yourself, please		
	write below who has these documents and your solicitor or estate		
	agent will arrange for them to be obtained. You will also need to		
	provide a description of the work carried out. This may be shown		
	in the original estimate.		
	Cuprantage and hold but		
	Guarantees are held by:		

14	Gu	arantees					
а	Are	there any guarantees or warranties for a	ny of	the fo	llowing?		
			No	Yes	Don't know	With title deeds	Lost
i)		Electrical Work	U				
ii)		Roofing	î/	,			
iii)		Central Heating					
iv)		National House Building Council (NHBC)					
v)		Damp course					
vi)		Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	<i>i</i> /				
		rou have answered 'Yes' or 'with title deec tallations to which the guarantee(s) relate		-			
С	Are	there any outstanding claims under any	of the	guara	antees	Yes	
	list	ed above?		_		No	//
	If y	ou have answered Yes, please give detail	s:			Unknown	
15		undaries					
		far as you are aware, has any boundary oved in the last 10 years?	r you	r prop	erty been	Yes No	
		ou have answered Yes, please give detail	c?			Unknown	
	11 Y	ou nave answered res, please give detail	<b>J</b> :				

16	Notices that affect your property		
In ti	ne past 3 years have you ever received notice:		
		Yes	
а	Advising that the owner of a neighbouring property has made a	No	V
	planning application?	Unknown	
		Yes	
b	That affects your property in some other way?	No	1
		Unknown	
		Yes	
С	That requires you to do any maintenance, repairs or	No	4
	improvements to your property?	Unknown	

If you have answered Yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

Date: 29.3.22